














Bois au détail

	<i>Dim.</i>	<i>Modèle</i>	<i>Essence</i>	<i>Ref.</i>
	9/90	<i>Latte Rob</i>	<i>S.R.N.</i>	<i>BA 010 090</i>
	16/90	<i>Rabotée 2 coins arrondis</i>	<i>S.R.N.</i>	<i>BA 016 090</i>
	22/140	<i>Rabotée 4 coins arrondis</i>	<i>S.B.</i>	<i>BA 022 140</i>
	34/90	<i>Latte Arr.</i>	<i>S.R.N.</i>	<i>BA 034 090</i>
	44/140	<i>Raboté coins arrondis</i>	<i>S.R.N.</i>	<i>BA 045 145</i>
	90/90	<i>Rabotté coins arrondis</i>	<i>S.B.</i>	<i>BA 095 095</i>
	120/120	<i>Rabottée coins arrondis</i>	<i>S.B.</i>	<i>BA 120 120</i>
	45/59	<i>Brut</i>	<i>S.B.</i>	<i>BB 048 063</i>
	63/175	<i>Brut</i>	<i>S.B.N.</i>	<i>BB 063 175</i>
	75/225	<i>Brut</i>	<i>S.B.N.</i>	<i>BB 075 225</i>
	15/88	<i>Lattes de porte</i>	<i>S.R.N.</i>	<i>BL 015 088</i>
	18/117	<i>Planches de toit</i>	<i>S.B.N.</i>	<i>BL 016 105</i>
	22/118	<i>Planche à clin</i>	<i>S.R.N.</i>	<i>BL 022 115</i>
	15/115	<i>Plancher (arrêtes vives)</i>	<i>S.B.N.</i>	<i>BL 017 110</i>
	28/130	<i>Plancher</i>	<i>S.R.N.</i>	<i>BL 028 130 a</i>
	28/145	<i>Planche de terrasse</i>	<i>S.R.N.</i>	<i>BZ 9828141</i>
	28/130	<i>Profil abri</i>	<i>S.R.N.</i>	<i>BL 028 130 b</i>
	34/130	<i>Profil abri</i>	<i>S.R.N.</i>	<i>BL 035 130</i>
	45/130	<i>Profil abri</i>	<i>S.R.N.</i>	<i>BL 045 130</i>
	58/130	<i>Profil abri</i>	<i>S.R.N.</i>	<i>BL 058 130</i>
	68/68	<i>Profil c (dormant de porte)</i>	<i>S.R.N.</i>	<i>BP 035 000</i>

